

Turbosound Speaker Firmware Update (06 Jan 2020)

iP300 (V1.2.2) & iP500 V2/ iP1000 V2/ iP2000 V2/ iP3000 (V2.2.2)

Addressed Issues

Item	Issues Description	Solution
1	Don't comply new Bluetooth chipset.	Update firmware to solve this issue.
2	Bluetooth function can't be shut down.	Add SHUT DOWN function to the DSP screen menu.