

Behringer RD-8 Firmware

Version 1.3.5 (9 March 2020)

Ticket Number	Summary
RD-605	Incorrect test shown when swapping modes
RD-604	Missing links in user interface contexts
RD-564	Audible noise on accented cymbals
RD-591	Step Repeat: Unwanted voices occasionally sound
RD-611	Primary & Secondary slave units go into different modes on Stop
RD-541	Start/Stop messages passed when USB -> MIDI switched off.
RD-587	Able to have the machine ignore SysEx messages and crash trying to import messages to none existent slots.
RD-561	Inserting pattern #2 in pattern chain mode doesn't register
RD-441	Difference between Copy and ERASE operations
RD-556	Slave unit not responding to Stop/Pause correctly
RD-502	MIDI Map: Playing multiple voices on the same trigger key only sounds one of the voices (leftmost on the unit)
RD-546	Factory Reset: Filter defaults to fully closed, not fully open
RD-619	Installing release build 1.3.2 and the device says firmware 1.2.2 is installed
RD-573	For release build 1.2.1 the version showing on the devices as 127.127.1
RD-590	Production tests: The RD-8 will assert when trying to place the unit into TEST mode
RD-567	No Start/Stop on RD-8 analogue clock
RD-571	RD-8 Crash cymbal significantly louder than Ride
RD-601	RD-8 Instability while writing patterns using develop build 380