



Behringer RD-9 Firmware

Version 1.0.6 (30 July 2021)

Improvements:

1. Fixed a bug that when powering on the RD-9 with MIDI IN data present it could cause the MIDI IN sync function to fail.
2. Fixed a typo in the LENGTH menu, it should be 'copied' instead of 'copyed'.
3. Lowered the HATS pitch a little in authentic mode.
4. HATS tune now changes instantly when switching from authentic mode to enhanced mode with BASS DRUM P.DEPTH and PITCH.
5. Fixed a bug in song mode where the wrong pattern/song data may be loaded.

Version 1.1.1 (18 Sep 2021)

Improvements:

1. Added compatibility for new bootloader