Embedded Software Release
for DL Series I/O Interfaces

MIDAS

DL8, DL32 Firmware V3.0
Release 2024-03-25

New Features

o BEHRINGER WING supported on both AES50 ports

Applying firmware 3.0 updates with a computer

1. Download firmware 3.0 from behringer.com.
2. Connect the powered-off device to the computer.
3. Turn on the device.
4. Run the firmware application on your computer. Wait for the firmware to be updated and unplug the USB connection.