



Behringer RD-6 Firmware

Version 1.0.6 (25 Mar 2022)

Improvements:

1. Fixed an issue that when the sequencer is playing, the user must select the new Pattern Group first then select Pattern Number. If the new Pattern Number is selected first and then the Pattern Group, the pattern number reverts to the currently playing pattern.